

**EXAMPLE INSPECTIONS LLC  
123 THOROUGH LANE  
NOWHERE NV 89XXX**

# NOTICE OF NON-COMPLIANCE

For Multiple Objects at One Location

(5 to 20 Objects per Packet)

This Report Must be Filed Within 10 Days per NAC 455C.522

1. Location Name	2. Location Address	3. Page No. <b>FIRST</b>
<b>COOL PLACE CASINO</b>	<b>456 EASY STREET LV NV</b>	1 of <b>3</b>
4. Owner	5. Inspection Date(s)	6. Date Rec'd by MCS
<b>MANNY EL EVATOR</b>	<b>4/24/17 – 4/28/17</b>	

The following items are found to be in Non-Compliance with **Chapter 455C of the NRS and/or NAC**. In the interest of safety and economy, and to conform to the applicable statutes and regulations, these items should receive your prompt attention. Once corrected IT IS IMPORTANT that you or your Authorized Agent notify the issuing AIA/Special Inspector in writing.

7. Equipment Type And State NV#	8. Item#	9. Standard, Regulation or Section of the Act of Non-Compliance and Description	10. Abatement Date (Max – 30 Days)	11. Completed Date
<b>EL #9876</b>	<b>1</b>	<b>GOVERNOR INOPERABLE</b> A17.1 2013 – 8.11.2.1.2 (FF)	<b>PERMIT HOLD</b>	
	<b>2</b>	<b>SAFETIES DIRTY</b> A17.1 2013 – 8.11.2.1.5 (J)	<b>5/2/17</b>	
	<b>3</b>	<b>DOOR LOCK OUT OF ADJUSTMENT</b> A17.1 2013 – 8.11.2.1.4 (b)	<b>5/2/17</b>	
	<b>4</b>	<b>DIRTY PIT</b> A17.1 2013 – 8.11.2.1.5 (A)	<b>5/24/17</b>	
<b>EL #9875</b>	<b>1</b>	<b>HOISTWAY DIRTY</b> A17.1 2013 – 8.6.4.7.1	<b>5/28/17</b>	
	<b>2</b>	<b>OIL SPILL IN PIT</b> A17.1 2013 – 8.11.3.1.5 (A)	<b>5/28/17</b>	
<b>ESC #2220</b>	<b>1</b>	<b>HANDRAIL DAMAGED</b> A17.1 2013 – 8.11.4.1 (C)	<b>5/3/17</b>	
<b>MW #4321</b>	<b>1</b>	<b>COMBPLATE DAMAGED</b> A17.1 2013 – 8.11.4.1 (G)	<b>A.D.I.</b>	<b>4/26/17</b>
<b>WCL #4477</b>	<b>1</b>	<b>RUNWAY CONSTRUCTION</b> A18.1 2011 – 10.2.2.3 (J)	<b>5/8/17</b>	

Equipment Type: **EL**- Elevator; **ESC**- Escalator; **MW**- Moving Walk; **DW**- Dumbwaiter; **WCL**- Wheel Chair Lift; **CL**- Chair Lift; **X**- Other

12. Total Item Count for This Page: **9**