# NEVADA OCCUPATIONAL SAFETY AND HEALTH REVIEW BOARD

\* \* \* \* \*

CHIEF ADMINISTRATIVE OFFICER
OF THE OCCUPATIONAL SAFETY
AND HEALTH ADMINISTRATION OF
THE DIVISION OF INDUSTRIAL
RELATIONS OF THE DEPARTMENT

Complainant,

OF BUSINESS AND INDUSTRY, STATE

VS.

OF NEVADA,

1

2

3

4

5

6

7

8

9

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

28

M. J. DEAN CONSTRUCTION, INC.

Respondent.

Docket No. LV 20-2003

Inspection No. 1391691

# DECISION AND ORDER OF THE BOARD FINDINGS OF FACT, CONCLUSIONS OF LAW AND FINAL ORDER

This case arose out of a referral alleging a safety violation at a construction site in Las Vegas. See, State's Exhibit 1, p. 3. The State's inspection resulted in the issuance of one citation consisting of one violation of federal regulations. See, State's Exhibit 1, pp. 41-52.

The matter came before the Nevada Occupational Safety and Health Review Board (the Board) for hearing at 10:30 a.m. on August 11, 2021. *See*, Tr. pp. 1, 45;3-9. The hearing was conducted in furtherance of a duly provided notice. *See*, Notice of Hearing dated December 10, 2020. In attendance to hear the matter were Board Chairman Rodd Weber, Board Secretary William Spielberg, Board Member Frank Milligan, Board Member Scott Fullerton and Board Member Jorge Macias. *See*, Tr. p. 48;8-12. The same Board Members deliberated the case after the conclusion of the hearing on the merits. *See*, Tr. pp. 210-219.

Salli Ortiz, Esq., counsel for the Chief Administrative Officer of the Occupational Safety and Health Administration of the Division of Industrial Relations of the Department of Business and Industry (the State), appeared at the hearing on behalf of the Complainant (the State). See, Tr. pp. 44;22-24. The Respondent (hereinafter, Respondent or M. J. Dean) was represented by Jim Kent (Mr. Kent) the Respondent's Safety Director. See, Tr. p. 44;15-21.

Jurisdiction in this matter is conferred by Chapter 618 of the Nevada Revised Statutes, NRS 618.315. Jurisdiction was not disputed. As there were five members of the Board present to decide the case, with at least one member representing management and one member representing labor in attendance, a quorum was present to conduct the business of the Board.

Nevada has adopted all Federal Occupational Safety and Health Standards which the Secretary of Labor has promulgated, modified or revoked and any amendments thereto. They are then deemed the Nevada Occupational Safety and Health Standards. See, NRS 618.295(8). A complaint may be prosecuted for circumstances which arise before or during an inspection of the employer's workplace. See, NRS 618.435(1).

The Notice of Alleged Safety or Health Violations generally alleged that Felipe de Jesus Ulna-Cortez (Mr. Cortez), an M. J. Dean employee, was injured as the result of a 20 foot fall while working on the 59<sup>th</sup> floor of the Resorts World Tower<sup>1</sup>. See, State's Exhibit 1, p. 3. Nevada OSHA alleged that two employees were installing plywood sheeting to prepare for form work, when one of the employees fell through a hole that would be used as a ladder access. A hole is defined in the regulations to mean "a gap or void 2 inches (5.1 cm) or more in its least dimension, in a floor, roof, or other walking/working surface." 29 CFR 1926.500(b). The instant hole was of a size which far exceeded this definition. See, Tr. p. 70;11-14, see also, State's Exhibit 1, p. 76. The hole had been covered with plywood but the cover had not been marked HOLE or COVER. See, State's

<sup>&</sup>lt;sup>1</sup>It was subsequently determined that the employee fell from the 61<sup>st</sup> floor and landed on the 59<sup>th</sup> floor of the tower. See, State's Exhibit 1, p. 50.

///

Exhibit 1, p. 35. Nevada OSHA issued a Citation and Notice of Penalty which recommended a \$6,300 fine. *See*, State's Exhibit 1, pp. 41-52.

On May 29, 2019, a Citation and Notice of Penalty was issued to the Respondent. See, State's Exhibit 1, p. 52. On April 26, 2019, the Respondent notified the State of its intent to contest the citation. See, State's Exhibit 1, pp. 53-55. On May 15, 2019, the State filed its formal Complaint for resolution by the Review Board. See, State's Exhibit 1, pp. 60-66.

Notice of the proceedings was given to M. J. Dean by first class, certified mail, return receipt requested. *See*, Notice of Hearing dated August 1, 2019. The hearing on the matter was subsequently rescheduled on three occasions. The Complaint alleges the violation of one Federal Regulation. *See*, State's Exhibit 1, pages 69-77. Citation 1, Item 1, charged a serious violation of 29 CFR 1926.502(i)(4), as stated below:

All covers shall be color coded or they shall be marked with the word "HOLE" or "COVER" to provide warning of the hazard.

On June 5, 2019, Mr. Kent, answered the Complaint for the Respondent. See, State's Exhibit 1, p. 64. Respondent's Answer alleged the citation was incorrect and without merit. The Respondent intended to show that no "hole" as defined by the regulation was present, negating the duty to cover, paint and/or mark the hole. See, Id. Additionally, the Respondent alleged that the employee was engaged in employee misconduct when he disconnected from his fall protection equipment. See, Id.

At the hearing on the matter, the State offered for admission its Exhibits 1-3, consisting of 172 pages. See, Tr. p. 49;2-7. The State's exhibits were admitted without objection. See, Tr. p. 54;8-11. The Respondent offered for admission 17 Exhibits of an unspecified number of pages. The State objected to the admission of all of the Respondent's exhibits because the discovery order was not followed and because many of them were not relevant to the violation. See, Tr. pp.50;7-9, 53;5-7. The Board decided to

take the State's objections under advisement and resolve any specific disputes during the course of the hearing.<sup>2</sup> See, Tr. p. 54;12-15.

### FINDINGS OF FACTS

M. J. Dean is a Nevada corporation authorized to do business in the State of Nevada. *See*, State's Exhibit 1, pp. 1-2. M. J. Dean 's principal place of business is 5055 W. Patrick Lane Ste. 101, Las Vegas, Nevada. *See*, State's Exhibit 1, pp. 1-2.

The construction site is known as Resorts World, located at 3000 Las Vegas Blvd., Las Vegas, Nevada (Resorts World). See, State's Exhibit 1, p. 3. W.A. Richardson Builders, LLC, (Richardson Builders) was the general contractor for the construction site. See, Tr. p. 66;13-15. M. J. Dean was one of the subcontractors at the Resorts World project. See, State's Exhibit 1, p. 5.

The Respondent's construction process at the Resorts World project is known as the flying form system, among other names. *See*, Tr. p. 120;10-15. In this process, concrete is poured and dries on a moveable platform, known as a form. *See*, *Id*. After the concrete is dry, the forms are retracted so they are no longer in contact with the concrete floor. Then the forms are flown, lifted from one floor to a higher floor of the building. *See*, Tr. p. 138;10-24, 139, 1-4. Once in place, the form is prepared to receive the concrete, *i.e.*, wet concrete is poured onto it. *See*, Tr. p. 120;10-14. This process is repeated until the building reaches its intended height. The Respondent's employees secure the area on top of the forms and prepare them for the pouring of wet concrete. *See*, Tr. pp. 138;10-24, 139; 1-4.

The Respondent's workers had two relevant tasks on the form. The first was to provide for worker safety by putting up railings around the outside and covering the holes. *See*, Tr. pp.140;24, 141;1-21. The second was to set up the block outs, areas where the concrete will not be poured. These penetrations are for things like heating and air conditioning ducts. While its workers are on the form, the Respondent requires each

<sup>&</sup>lt;sup>2</sup>During the hearing, the Respondent utilized several of the documents and photographs it had offered. As these documents were utilized in the proceedings, they are deemed to have been admitted.

employee to wear appropriate fall protection. *See, Id.* This protection consisted of a retractable tie that attached to the building and a full body harness for the worker. *See*, Tr. pp.139;10-13.

On March 18, 2019, Mr. Cortez needed a piece of plywood that was beyond his reach while wearing his fall protection equipment. *See*, Employer's Exhibit 7, pp. 26, 27. Mr. Cortez took his safety harness off to access the piece of plywood. *See*, *Id*. He grabbed the piece of plywood then fell through a hole. *See*, *Id.*, *see also*, Tr. pp. 62;2-3, 131;2-6. This opening was predetermined to be the Respondent's ladder access from the lower floor. *See*, Tr. pp. 164;21-24; 165;1-2. The hole had been covered with plywood but the cover was not color coated or marked HOLE or COVER.<sup>3</sup> Mr. Cortez fell from the 61<sup>st</sup> floor and landed on the 59<sup>th</sup> floor, suffering a laceration to the head and bruising of the upper torso and arms. *See*, State's Exhibit 1, p. 50.

On March 19, 2019, Nevada OSHA inspector Berly Carrillo (Mr. Carrillo) went to the Resorts World construction site in response to the referral. See, State's Exhibit 1, p. 3, see also, Tr. pp. 57;20-24; 58;1-3. The opening conference was conducted with Shelby Burton (Ms. Burton) of Richardson Builders and Raymond Milner of M. J. Dean. See, State's Exhibit 1, pp. 4, 5. Both Ms. Burton and Mr. Milner signed the employers' Opening Conference Worksheet acknowledging that they understood their rights and consented to an inspection of the construction site. See, Id.

In her interview, Ms. Burton stated that Mr. Cortez was part of the flyer crew. *See*, Tr. p. 66;19-24. Mr. Cortez fell through the hole located on the 61<sup>st</sup> floor. Directly below this opening was another opening going from the 60<sup>th</sup> floor to the 59<sup>th</sup> floor. Mr. Cortez passed through this second opening and landed on the 59<sup>th</sup> floor. *See*, State's Exhibit 1, p. 18, *see also*, Tr. p. 66;19-24.

After the opening conference, Mr. Carrillo inspected the construction site. At the location where Mr. Cortez fell, Mr. Carrillo discovered that the hole through which Mr.

<sup>&</sup>lt;sup>3</sup>The citation does not address whether the cover to the hole was secured. The testimony indicated that it was not. However, the State did not cite the Respondent for this issue.

///

<sup>4</sup>The transcript incorrectly identifies this exhibit as being State's Exhibit number 35. See, Tr. p. 74;7-10.

Cortez fell had been made into a ladder access from the 60<sup>th</sup> floor to the 61<sup>st</sup> floor. See, State's Exhibit 1, p. 72, see also, Tr. p. 69;2-11. This ladder access had a guardrail system in place. See, State's Exhibit 1, p. 73, see also, Tr. p. 69;12-15. However, all of the persons interviewed agreed that the guardrail system was not in place at the time of Mr. Cortez' accident. See, Tr. p. 69;16-19.

The addition of the guardrail system did not prevent Mr. Carrillo from analyzing the alleged violation because he supplied photographs taken as part of the employer's accident investigation. *See*, State's Exhibit 1, pp. 77-79. Several of these photographs were included in the State's Exhibit 1. *See*, Tr. pp. 70;15-22, 71;110. Three of the photographs provided relevant information. The first showed the location of the hole at the time of the accident. The picture did not show any color coding or labeling on the hole. *See* State's Exhibit 1, p. 77. The second showed the plywood that was covering the hole on the 61<sup>st</sup> floor, as it was found after the accident. *See* State's Exhibit 1, p. 78. Again, the photograph showed that the cover was neither color coded nor labeled. *See*, *Id*. The third photograph was another picture of the location of the unmarked hole on the 61<sup>st</sup> floor. *See*, State's Exhibit 1, p. 79.

After the inspection, the Respondent supplied its form 300 (Injury and Illness logs) and 300A (certified summaries) for the years 2016, 2017 and 2018. Those forms disclosed that a similar incident had occurred in November of 2018, about four months before the instant accident. *See*, State's Exhibit 3, p. 140. In this earlier incident, the employee pulled the nails out of an unmarked plywood cover and fell through the hole. *See*, State's Exhibit 3, p. 144. One of the recommendations made by the general contractor subsequent to this injury was to "mark and secure all hole covers to insure that nobody accidently mistakes hole covers as fill material." *See*, State's Exhibit 3, p. 145, *see also*, Tr. p. 74;7-13.4

8

7

11 12

10

13 14

16

15

1718

19 20

21

22

23

24

2526

27 28 At the hearing on the matter held on August 11, 2021, Mr. Carrillo testified to the above. He was then cross examined by Mr. Kent. See, Tr. pp. 76-98. In this cross examination, Mr. Carrillo was asked about the Respondent's fall protection rules and related safety documents. See, Employer's Exhibits 1 through 5. Mr. Carrillo was not completely familiar with the documents but, based upon Mr. Kent's description of the Employer's documents, Mr. Carrillo conceded that M. J. Dean had met its obligation for fall protection training. See, Tr. pp. 82;15-24, 83;1-2.

Mr. Kent further questioned Mr. Carrillo regarding the final passage of this narrative. See, State's Exhibit 1, p. 19, see also, Tr. p. 87;14-22. Therein, Mr. Carrillo stated, "it was determined that the employee fell through a hole because the employee disconnected his fall protection equipment...However, it was also determined that the employee fell through a hole on the floor for the hole cover had not been marked 'hole' or 'cover.'" Mr. Kent took this comment to indicate that the regulation provided for alternative methods of compliance. The employer could either provide fall protection equipment or mark all of the hole covers. See, Tr. pp. 87-88. To bolster his allegation, Mr. Kent provided what appeared to be a page from a Federal OSHA document which defined both a hole and an unprotected edge.5 See, Employer's Exhibit 8. "Unprotected sides and edges mean any side or edge ... of a walking or working surface, e.g., floor, roof, ramp or runway where there is no wall or guardrail system at least 39 inches (1.0 m) high." See, Id. Through these questions, Mr. Kent implied that the fall protecting requirements for a leading edge should have been applicable to the entire 61st floor at the time of Mr. Cortez' accident. See, Tr. p. 97;12-19. Based upon this interpretation, the unmarked hole cover did not violate any Federal regulation.

Mr. Kent then followed up these questions by inquiring as to whether Nevada OSHA should have considered employee misconduct. See, Employer's Exhibit 11, see

<sup>&</sup>lt;sup>5</sup>The Respondent did not supply any information regarding the source of this document. It appears to be a from a Department of Labor, OSHA website. However, the date of publication and its publisher were not provided.

27

28

<sup>&</sup>lt;sup>6</sup>Leading edge means the edge of a floor, roof, or formwork for a floor or other walking/working surface (such as the deck) which changes location as additional floor, roof, decking, or formwork sections are placed, formed, or constructed. A leading edge is considered to be an "unprotected side and edge" during periods when it is not actively and continuously under construction. 29 CFR 1926.500(b).

serious because serious injuries could result from a fall from a height of 20 feet. See, Tr.

p. 116;8-17. Mr. Sayegh further testified that the severity factor was high because such

27

28

fall could result in death, permanent disability or permanent impairment of an employee. See, Tr. pp. 116;22-24, 117;1-9. The State found probability of injuries from the hazard to be "greater." See, Tr. p. 100;5-16. The probability of injury is a function of the number of employees involved or exposed to the condition, how often the employees are exposed and similar factors. See, Tr. p. 117;12-23. In this instance, two workers were exposed to the hazard. The employee proximity was given a rating of ten because they were working at the point of danger. See, Tr. p. 117;19-21. The frequency of exposure was given a ten also because it was being done on a daily basis as a regular part of their job. See, Tr. p. 117;18-23. The gravity of the violations is the starting point for the calculation of the penalty. The gravity of the violation is a function of the probability of an injury and the severity of the injury, should one occur. See, Tr. pp. 117;24, 118;1-5. This was a gravity based penalty with a starting amount of \$7,000. See, Tr. p. 118;6-11. This gravity based penalty was then reduced to \$6,630, as the result of the Respondent's size and its history. See, Tr. p. 118;12-21.

The State's next witness was Chris Otto (Mr. Otto), the Respondent's superintendent of the job site on the day of the inspection. See, Tr. pp. 127;17-24, 128;1-2. During the inspection, Mr. Otto gave a statement, wherein he provided two relevant comments. See, State's Exhibit 1, pp 30-31. The first was that there was a hole for ladder access which should have been nailed down and marked "hole." See, Id. The second was actually an internal contradiction. At one point, Mr. Otto said that Mr. Cortez was responsible for nailing it down. See, Id. However, a few lines below, Mr. Otto stated that there is no designated person for marking the cover. See, Id.

Mr. Otto was also questioned about the form entitled "Daily Pre-Task Planning Sheet" (Planning Sheet) Dated 3-18, (March 18, 2019). See, State's Exhibit 3, p. 132. Specific to this inquiry is the statement, "Be sure to ask the following when evaluating your work...[a]re all holes covered marked and secured?" See, Id. The response to this question was affirmative, the "yes" was circled. See, Id. Mr. Otto responded that this form is Xerox copy, most likely created by Mr. Kent and the Safety Officer. See, Tr. p. 136;3-

13.

1

2

3

5

7

10

11

12

13

14

15

16

17

18

19

20

21

22

23

24

25

26

27

The State's next witness was Sergio Resendiz (Mr. Resendiz), who was the deck foreman at the time of the accident. See, Tr. pp. 174-175. Mr. Resendiz testified that he signed the Planning Sheet for March 18, 2019, the day of the accident. See, Tr. p. 176;4-13. Mr. Resendiz indicated that the Planning Sheet was filled out at the start of the day. See, Tr. p. 176;14-17. Accordingly, the statement that "all holes covered marked and secured" was applicable to the 60<sup>th</sup> floor, as opposed to the 61<sup>st</sup> floor. This was because the 61<sup>st</sup> floor had not been created at the time that Mr. Resendiz completed the form. See, Tr. p. 176;17-24.

Mr. Resendiz provided conflicting testimony regarding responsibility for securing and marking the hole. In one instance he testified that Mr. Cortez and his partner, "had plenty of time to nail that plywood down. So if that plywood was not nailed... those are the guys that put it together." See, Tr. p. 184;10-16. However, Mr. Resendiz later testified that another group of workers would nail down the plywood over the hole. "Somebody from flyer crew would have to come back after the deck was sheeted to mark the hole." See, State's Exhibit 1, p. 25.

In deliberations, the Board Members made comments on the evidence supplied by the parties. See, Tr. pp. 210-212. Board Member Fullerton provided a couple of comments which exposed flaws in the Respondent's argument that the regulation provided alternative methods of compliance. First, he explained why covering and marking a hole are necessary even when working in close proximity to a leading edge and wearing fall protective devices.

The other aspect of it is when they talk about the other areas with the leading edge where the joists are, the reason that those aren't marked is because that is a clear and visible danger. Guys don't walk between those joists because they know they can't walk on air. The intent of marking that covered area as a hole is because it is not a clear and visible danger at that point, and the intent of that is to keep somebody from inadvertently taking that piece of plywood or even walking on a piece of plywood that would not be secure enough to support their weight. See, Tr. Pp. 211;22-24, 212;1-7.

28

///

 Further, Board Member Fullerton explained why covering and marking holes are valuable even when full fall protection is utilized.

The idea is even with that support that marking is to keep you from walking in there and suffering even minor abrasions. You know, the fall protection is going to protect you from the serious injury, but it's still not going to protect you from some minor injuries that you may have sustained through that accident. See, Tr. p. 212;17-22.

After the Board seemed to reach a consensus that the first three elements of the State's *prima facie* case were met, it went on to discussed the employer's knowledge of the violative conduct. Towards that end, the Members brought up an issue which the State had not discussed, the location of the accident. *See*, Tr. pp. 213;20-24, 214;1-15. The unmarked hole was located on the 61<sup>st</sup> floor. *See*, Tr. pp. 213;20-24, 214;1-15. Each floor of the 60 lower floors is presumed to have had ladder access in a similar location on the floor. *See*, *Id*. The ladder accesses need to be created, covered, marked and eventually enclosed on each of the lower floors. This activity would have occurred on almost a daily basis which should have informed the employer that securing and covering the holes on each floor is required. *See*, *Id*.

#### CONCLUSIONS OF LAW

The burden is on the State to prove by a preponderance of the evidence, a prima facie case against the Respondent. See, NAC 618.788(1), see also, Original Roofing Company LLC v Chief Administrative Officer of the Nevada OSHA, 442 P. 3d 146, 149, (Nev. 2019). Thus, in matters before the Board of Review, the State must establish (1) the applicability of a standard being charged; (2) the presence of a non-complying condition; (3) employee exposure or access to the non-complying condition; and, (4) the actual or constructive knowledge of the employer's violative conduct. Id. at 149, see also, American Wrecking Corp. v. Secretary of Labor, 351 F. 3d 1254, 1261 (D. C. Cir., 2003).

The State is obligated to demonstrate the alleged violation by a preponderance of the reliable evidence in the record. Mere estimates, assumptions and inferences fail this test. Conjecture is also insufficient. Findings must be based upon the kind of the evidence upon which responsible persons are accustomed to rely in serious affairs. *William B*.

2 3 4

Hopke Co., Inc. 1982 OSHARC LEXIS 302 \* 15, 10 BNA OSHC 1479 (No. 81-206, 19820 (ALJ). The Board's decision must be based on consideration of the whole record and shall state all facts officially noticed and relied upon. 29 CFR 1905.27(b). Armor Elevator Co., 1 OSHA 1409, 1973-1974 OHSD ¶ 16, 958 (1973). Olin Construction Inc. v. OSHARC and Peter J Brenan, Secretary of Labor, 525 F. 2d 464 (1975). A Respondent may then rebut the allegations by showing, 1) the standard was inapplicable to the situation at issue or 2) the situation was in compliance. S. Colorado Prestress Co. v. Occupational Safety & Health Rev. Comm'n, 586 F.2d 1342, 1349–50 (10th Cir. 1978).

The State met its burden to show that M. J. Dean violated 29 CFR 1926.652 because it provided testimony and photographs showing that there was an opening with a dimension in excess of 2 inches. *See*, 29 CFR 1926.500(b). In fact, this opening was 40 by 42 inches. *See*, Tr. p. 70;11-14, *see also*, State's Exhibit 1, p. 76. The condition was non-compliant because the cover was neither color coded nor marked HOLE or COVER. *See*, State's Exhibit 1, pp. 25, 26, 27, 29, 30. In this instance, employee exposure is proven, because M. J. Dean, had two employees installing plywood sheeting to prepare for form work within a few feet of this hole. Exposure is shown because Mr. Cortez did not see the hole and fell 20 feet 3 inches to the 59<sup>th</sup> floor, suffered a laceration to the head and suffered a bruise of the upper torso and arms. *See*, State's Exhibit 1, pp. 24, 25, 26, 27.

The final element of the State's *prima facie* case, employer knowledge, is shown in several ways. First, the Respondent requires its managers to fill out a Daily Pre-Task Planning Sheet which expressly requires that all holes are covered and marked. *See*, State's Exhibit 3, p. 132, *see also*, Tr. p. 136;3-9. The daily use of this form, alone, showed the Respondent understood that covering and marking holes are continuing requirements. Moreover, one of the Respondent's employees suffered a very similar accident on this same job site four months before. *See*, State's Exhibit 3, p. 140. One of Richardson Builders' recommendations made subsequent to this injury was to "mark and secure all hole covers to insure that nobody accidently mistakes hole covers as fill

subsequent recommendation was to show that the Respondent knew of the hazardous condition, unmarked holes, before Mr. Cortez' injury. See, Tr. pp. 74;18-24, 75;1-5.

Based upon the above, the Respondent's knowledge of the standard was established.

In its defense, M. J. Dean provided two arguments. The first was a variant of the

material." See, State's Exhibit 3, p. 145. The relevance of this previous accident and

In its defense, M. J. Dean provided two arguments. The first was a variant of the inapplicable standard defense. The Respondent alleged that the work environment was such that the entire deck should be considered a leading edge. See, Tr. pp. 206;7-22, 207;1-7. Therefore, the Respondent provided sufficient protection by training all of its employees in the use of fall protection equipment and required them to use it. See, Tr. p. 207;8-22.

The Respondent's argument fails because the opening met with the regulatory definition of a hole. See, 29 CFR 1926.500(b). The opening had dimensions of 40 by 42 inches. See, Tr. p. 70;11-14, see also, State's Exhibit 1, p. 76. Thus, under the plain meaning of the regulation, there was a hole that needed to be labeled. See generally, Valley Camp of Utah, Inc. v. Babbitt, 24 F.3d 1263, 1270 (10th Cir. 1994)(Regulations are interpreted by applying general rules of statutory construction, beginning with the plain language of the regulation), see also, Aspenwood Investment Co. v. Martinez, 355 F.3d 1256, 1261 (10th Cir. 2004). The plain meaning of the regulation overrode, the more general requirement that the employees must use fall protection. As the opening was a hole, as defined by the regulations, the Respondent was required to mark it as "hole" or "cover."

The Respondent's other defense was unpreventable employee misconduct. This defense necessarily failed because there was no nexus between the violation and the misconduct. In order to invoke this defense, the employer must prove, *inter alia*, that it had established work rules to prevent the violation and it effectively enforced violations when discovered. *D.A. Collins Const. Co. v. Sec'y of Lab.*, 117 F.3d 691, 695 (2d Cir. 1997).

In this instance, M. J. Dean did not show that it had any work rules to prevent

unsecured and unmarked holes. Moreover, Mr. Cortez was not disciplined for failing to label the hole. Instead he was disciplined for not being tied off on the 61<sup>st</sup> floor. *See*, Employer's Exhibit 12, *see also*, Tr. p. 95;8-23. Thus, this defense was unavailable to the Respondent.

The Board accordingly finds and concludes that the preponderance of the evidence reveals the State met its *prima facie* burden under 29 CFR 1926.502(i)(4). Further, the evidence reveals that neither of the Respondent's affirmative defenses was applicable. The claim and penalty are hereby sustained.

#### ORDER

It was moved by Board Member Fullerton that the citation for a violation of 29 CFR 1926.502(i)(4) and the fine of \$6,300 be upheld. See, Tr. p. 219;7-12. The motion was seconded by Board Member Macias. See, Tr. p. 219;13-16. The motion was approved unanimously upon a vote of five in favor and none in opposition. See, Tr. p. 219;19-23. Accordingly, the State OSHA Board of Review hereby upholds the citation and fine assessed against M. J. Dean.

This is the Final Order of the Board.

IT IS SO ORDERED.

On December 15, 2022, the Board convened to consider adoption of this decision, as written or as modified by the Board, as the decision of the Board.

Those present and eligible to vote on this question consisted of the full current members of the Board, to-wit, Chairman Rodd Weber, William Speilberg, Frank Milligan, Jorge Macias and Scott Fullerton. Upon a motion by William Speilberg, seconded by Frank Milligan, the Board voted 5-0 to approve this Decision of the Board as the action of the Board and to authorize Chairman Weber, after any grammatical or typographical errors are corrected, to execute, without further Board review of this Decision on behalf of the Nevada Occupational Safety and Health Review Board. Those voting in favor of the motion either attended the hearing on the merits or had in their possession the entire record before the Board upon which the decision was based.

On December 15, 2022 this Decision is, therefore, hereby adopted and approved as the Final Decision of the Board of Review.

Dated this Sday of June, 2023.

NEVADA OCCUPATIONAL SAFETY AND HEALTH REVIEW BOARD

Rodd Weber, Chairman

## CERTIFICATE OF SERVICE

Pursuant to NRCP 5(b), I certify that I am an employee of the Law Offices of Charles R. Zeh, Esq., and that on this date I served the attached document, *Decision and Order of the Board, Findings of Fact and Conclusion of Law, and Final Order*, on those parties identified below by placing an original or true copy thereof in a sealed envelope, certified mail/return receipt requested, postage prepaid, placed for collection and mailing in the United States Mail, at Reno, Nevada:

Salli Ortiz, Esq. DIR Legal 400 West King Street, Suite 201 Carson City, NV 89703

Jim Kent 5055 W. Patrick Lane Ste. 101 Las Vegas, NV 89118

Dated this 25 day of August, 2023.

Employee of
The Law Offices of Charles P. Zeb. Ess.

The Law Offices of Charles R. Zeh, Esq.

S:\Clients\OSHA\LV 20-2003, M.J. Dean Construction, Inc\Decision R10.wpd